










Berlingo III 09/2018 >

Partner III 09/2018 >

Combo 06/2018 >

504138700001

504139700001



- HM8x25 cl 8.8 x 6
- CS 8 x 22 x 6
- [Image of a washer] x 6






- [Image of a hook] 13
- [Image of a cup] 13







- [Image of a screwdriver] 0-20 Nm
- [Image of two people]

504 138 700 001 - 504 139 700 001

07/07/2020





01 / 06





L1 / L2





13



20 Nm



13

